

art. 0839/302.06 no longer available



art. 0839/303.06

**Switching module
art. 0839/302.06**
is no longer available
due to exhaustion of stocks.

Therefore we now supply, as per
the replacement programme,
**Switching Module
art. 0839/303.06**